

TRABZON'DA RÜZGÂR AFETİ VE ETKİLERİ

Mine Candar

İl Afet ve Acil Durum Müdürlüğü, Trabzon, Türkiye, mtekbascandar@gmail.com.

Trabzon ilçelerinde 2010 yılı Aralık ayı itibariyle şiddetli esen rüzgarlara bağlı olarak farklı ilçe ve köylerde bulunan konut çatılarında ve konut dış cephelerinde tamamen yada kısmi suretle hasarlar meydana gelmiştir. Trabzona bağlı Araklı ilçesi Erikli köyünde 13 konut, Bahçecik köyünde 1 konut, Çaykara ilçesi Arpaözü köyünde 11 konut, Karaçam, Turnalı, Baltacılı, Çayıroba, Yaylaönü, Taşören Köylerinde de konutlar rüzgar afetinden dolayı çatılarının uçması suretiyle hasar görmüşlerdir. Sac çatı kaplama uygulamaları Trabzon köy konutlarında yaygın olarak kullanılmaktadır. Sürekli ikamet edilmesinin yanısıra, mevsimlik olarakta kullanılan bu konutlarda; uygulama kolaylığı, yüksek kalite ve düşük maliyet gibi pozitif etkenlerden dolayı sac çatı kaplamaları tercih edilmektedir. Yapılan arazi çalışmalarında hasar gören konutların çoğunun çatılarının sac kaplama olduğu belirlenmiştir. Dış cephelerde ise yan duvarlar hasar görmüş olup yüzey kaplamaların yerinden çıktığı belirlenmiştir.

Anahtar Kelimeler: Trabzon, konut, rüzgar, çatı uçması

THE EFFECTS AND WIND DISASTER IN TRABZON

Mine Candar

İl Afet ve Acil Durum Müdürlüğü, Trabzon, Türkiye, mtekbascandar@gmail.com.

Trabzon districts as of December 2010 due to fierce winds the roofs of houses in different towns and villages and residential damage occurred in the outer walls thus completely or partially. Araklı district of Trabzon, Erikli in the village of 13 houses, 1 house in the village of Bahçecik, 11 houses in the village of Arpaözü- Çaykara town, , Karaçam, Turnalı, Baltacılı, Çayıroba, Yaylaönü, Taşören villages disaster due to wind damage to roofs of houses have seen fly through. Sheet roofing applications is widely used in village houses of Trabzon. Permanent residence alongside of being used as seasonal residences in this; ease of implementation, high quality and low cost due to factors such as the positive sheet roof coatings are preferred. Sheet covering most of the rooftops of houses in the area were damaged by the work. Exteriors of the side walls were damaged and out over the surface coatings.

Key Words: Trabzon, house, wind, roof fly.